

Boston Public Library - Fields Corner Branch Dorchester, Massachusetts

Repairs to this neighborhood branch of the Boston Public Library built in 1969.

The scope of work included: Roof Repair/flashing at roof edges, hatch, vent, curbs, and roof drains. The additional scope of work included repairs to the roof fence.

The interior scope included: Renovation/repair of existing ceiling and interior lighting fixtures with the introduction of new interior soffits.

Address: 1520 Dorchester Avenue, Dorchester, MA

Project Architect: Charles Bradley, III, AIA (as an employee of Primary Group, Inc.)

